



Annealing of Cold-Worked Metal

- Annealing of the cold worked structure at high temperature softens the metal and reverts to a strain-free condition.
- The transformations that take place during annealing are **recovery**, **recrystallization** and **grain growth**, respectively.
- The **driving force** for recovery and recrystallization is the energy of the defects introduced during cold working (stored energy of the deformed matrix).
- The **driving force** for grain growth is the **boundary curvature**.



Annealing of Cold-Worked Metal



3 Annealing stages

Effect of 1 hour heating on mechanical properties

Recovery

**Recrystallization
nucleation and
growth of strain
free grains**

Grain growth





Fig. 1.1. Schematic diagram of the main annealing processes; (a) Deformed state, (b) Recovered, (c) Partially recrystallized, (d) Fully recrystallized, (e) Grain growth and (f) Abnormal grain growth.


Recovery

Annihilation reduces dislocation density.



Scenario 1



Scenario 2



Recrystallization


New crystals are formed that:

- have a small dislocation density
- are small
- consume cold-worked crystals.



Further Recrystallization

All cold-worked crystals are consumed.






Variables Affecting Recrystallization

- 1) The amount of prior deformation
- 2) Temperature
- 3) Time
- 4) Initial grain size
- 5) Composition
- 6) Amount of recovery prior to start the recrystallisation.

Recrystallization temperature can be defined as the temperature at which a given alloy in a highly cold-worked state completely recrystallizes in 1 h.



Grain Growth

- At longer times, larger grains consume smaller ones.
- Grain boundary area (and therefore energy) is reduced.

